

Shen Zhao¹ (zhaos@frib.msu.edu), Dan Morris¹, Harsh Maniar¹ ¹Facility for Rare Isotope Beams (FRIB), Michigan State University, East Lansing, MI 48824, USA

Tuner Control

Stepper

Problem: During the ReA6 2 cavity cryo-module 24 hour test, original stepper/piezo driver board stopped driving causing trips.

Root cause: Small chip package handles several watt power without proper heat management, eventually overheated.

Solution: Copper pour and heat sinks were added on both sides of the PCB.

Since the micro-stepping feature of the stepper driver is verified, piezo driver is removed.

	ReA6	High Speed	Low Speed	Trinamic
Accel Current (A)	1.36	1.57	2.37	1.3
Run Current (A)	2.04	2.37	1.57	1.0
Holding Current (A)	0.44	0.51	0.51	0.4
Run Condition	< 50%	Continuous	Continuous	Tuning Range Test
Test Time (hrs)	24	17	25	< 1

Pneumatic

Analog tuner board provides two 0 ~ 5 V analog output channels to control the pressure and vacuum valves for the tuner manifold.

Valve calibration procedure based on ANL procedure:

Dead-zone calibration:

- Set pressure valve close voltage so that pressure increase at <u>0.001 -</u> 0.002 psi/sec rate;
- Set vacuum valve close voltage so that pressure is stable;

Maximum tuning speed setting:

- Set pressure valve open voltage so that pressure increase at <u>0.2 - 0.3</u> psi/sec rate;
- Set vacuum valve open voltage so that pressure decrease at <u>0.2 - 0.3</u> psi/sec rate.







FRIB LLRF Control: Issues and Improvements

Internal Variable Overflow

<u>Problem</u>: During the ReA6 2 cavity cryo-module 24 hour test, amplitude control was found not stable at certain set-points during ramp up.



Design Changes

Remove one Digital to Analog Converter (DAC)

- Cost reduction (trade one RF switch for one DAC)
- Free 29 input/output pins

Remove analog board

- Easier installation

Add EEPROM to RF board

Address the LLC interlock false trigger issue

- low level control PLC
- Add opto-isolator to the AMP_STATUS signal
- Layout changes to reduce crosstalk

Reboot phase calibration

Add chassis fan/filter

Better cooling, reduce dust accumulation

Facility for Rare Isotope Beams

U.S. Department of Energy Office of Science Michigan State University



RF Control

<u>Root cause:</u> Amplitude control loop Internal variable overflows.



• Remove one FPGA (Spartan 3E), less firmware to maintain

Device calibration data can be stored local for easy swap

• Add capacitor to filter noise on 24 V signal provided by the

Add RF output feedback path to spare input channel

Lorenz Force Detuning (LFD)

<u>Problem:</u> During the HWR53 integrated test, it was hard to lock the cavity.

Root cause: Significant LFD effects at high field.

Solution: Good amplitude regulation is critical to minimize LFD effect; slower ramp rate help keeping cavity locked.

Smooth Switching between Open and Close Loop

<u>Problem:</u> In some of the tests, it was found that when closing the RF control loop, the system with trip.

Root cause: Sudden control effort change causes trip events.

Solution: Smooth switch was implemented in the control algorithm.

Interlocks for RFQ Conditioning

Quick shut off time

To protect RFQ from damage due to driving high power into the cavity when a spark happens, a fast interlock was implemented to turn off RF in less than 5 microseconds.

Interlock Rate Interlock

The user can select a set of interlocks of interest to be monitored for high interlock rate. If the number of interlocks happen in a defined time window exceeds the threshold, the interlock rate interlock will trigger.

This material is based upon work supported by the U.S. Department of Energy, Office of Science under Cooperative Agreement DE-SC0000661.







